

## CEA001—EXPERT COREY 200 FLEECE JACKET

MEASURING POINTS IN INCHES				XS		S		M		L		XL		XXL		3XL		
GARMENT MEASUREMENTS																		
A	FULL CHEST CIRCUMFERENCE (2" below armhole)			40		42		44		47		50		53		56		
D	CB LENGTH			27		27		28		28		29.5		29.5		30		
H	SLEEVE LENGTH (from neck point to end of cuff)			30.5		31		31.5		32		32.5		33		33.5		